



King's Research Portal

DOI:

[10.1016/j.jaccas.2019.11.086](https://doi.org/10.1016/j.jaccas.2019.11.086)

Document Version

Publisher's PDF, also known as Version of record

[Link to publication record in King's Research Portal](#)

Citation for published version (APA):

Patterson, T., Rajani, R., Esposito, G., Allen, C., Adams, H., Prendergast, B., ... Young, C. (2020). Transcatheter Aortic Valve-in-Valve Implantation Complicated by Aorto-Right Ventricular Fistula. *Journal of the American College of Cardiology: Case Reports*, 2(2), 309-311. <https://doi.org/10.1016/j.jaccas.2019.11.086>

Citing this paper

Please note that where the full-text provided on King's Research Portal is the Author Accepted Manuscript or Post-Print version this may differ from the final Published version. If citing, it is advised that you check and use the publisher's definitive version for pagination, volume/issue, and date of publication details. And where the final published version is provided on the Research Portal, if citing you are again advised to check the publisher's website for any subsequent corrections.

General rights

Copyright and moral rights for the publications made accessible in the Research Portal are retained by the authors and/or other copyright owners and it is a condition of accessing publications that users recognize and abide by the legal requirements associated with these rights.

- Users may download and print one copy of any publication from the Research Portal for the purpose of private study or research.
- You may not further distribute the material or use it for any profit-making activity or commercial gain
- You may freely distribute the URL identifying the publication in the Research Portal

Take down policy

If you believe that this document breaches copyright please contact librarypure@kcl.ac.uk providing details, and we will remove access to the work immediately and investigate your claim.

IMAGING VIGNETTE

INTERMEDIATE

CLINICAL VIGNETTE

Transcatheter Aortic Valve-in-Valve Implantation Complicated by Aorto-Right Ventricular Fistula



Tiffany Patterson, MBBS, PhD,^a Ronak Rajani, MBBS, MD,^b Giulia Esposito,^a Christopher Allen, MBBS,^a Heath Adams, MBBS(HONS), BMedSci,^b Bernard Prendergast, MBBS, MD,^b Christopher Young, MD,^b Simon Redwood, MBBS, MD^a

ABSTRACT

We describe the case of a degenerative, sutureless bioprosthetic valve (BPV) with deformation and stent infolding in a patient with elevated surgical risk. Following discussion among the heart team, balloon valve fracture was performed to facilitate deployment of an aortic valve-in-valve transcatheter heart valve. Post-procedural imaging demonstrated BPV frame protrusion and contained annular rupture, which required operative intervention. (**Level of Difficulty: Intermediate.**) (J Am Coll Cardiol Case Rep 2020;2:309–11) © 2020 The Authors. Published by Elsevier on behalf of the American College of Cardiology Foundation. This is an open access article under the CC BY license (<http://creativecommons.org/licenses/by/4.0/>).

An 81-year-old female presented with New York Heart Association functional class III symptoms of breathlessness. She had undergone implantation of a 19-mm Perceval (LivaNova, Markham, Ontario, Canada) sutureless bioprosthetic valve (BPV) 2 years previously for high-risk severe native aortic stenosis. Computed tomography (CT) demonstrated stent infolding and collapse (**Figure 1A**). Transthoracic echocardiography confirmed degenerative BPV failure with severe valvular and paravalvular aortic regurgitation (**1**). Coronary angiography demonstrated unobstructed coronary arteries with fluoroscopic confirmation of valve design (**Figure 1B**). Following review of the imaging and clinical history, the heart team consensus was to proceed with aortic valve-in-valve transcatheter heart valve (THV) implantation using a 23-mm Sapien S3 (Edwards Lifesciences, Irvine, California) and previous fracture of the distorted bioprosthetic valve frame. The valve-in-valve procedure was performed through the transfemoral route under transesophageal echocardiographic (TEE) guidance. BPV crossing was performed using a pigtail catheter exchanged for a standard curved Safari wire (Boston Scientific, Marlborough, Massachusetts) for support. Bioprosthetic valve fracture was performed successfully using a 20-mm Atlas Gold (CR Bard, Murray Hill, New Jersey) balloon dilation catheter (**Video 1**). A 23-mm Sapien 3 (Edwards Lifesciences) THV was then deployed at nominal volume under rapid pacing at 210 beats/min on the Safari wire (Boston Scientific) (**Figure 1C**, **Video 2**). After THV implantation imaging demonstrated no paravalvular leakage, however, there was suggestion of a contained rupture and

From the ^aCardiovascular Division, The Rayne Institute British Heart Foundation Centre of Research Excellence, King's College London, St. Thomas' Hospital, London, United Kingdom; and the ^bCardiothoracic Department, Guy's and St. Thomas' National Health Service Foundation Trust, London, United Kingdom. Supported by British Heart Foundation Clinical Research Training Fellowship grants FS/14/11/30526 (to Dr. Patterson) and FS/18/48/33745 (to Dr. Allen) and a U.S. National Institutes of Health Research Academic Clinical Lectureship (to Dr. Patterson). Dr. Redwood is a proctor for Edwards Lifesciences. All other authors have reported that they have no relationships relevant to the contents of this paper to disclose.

Informed consent was obtained for this case.

Manuscript received October 9, 2019; revised manuscript received November 21, 2019, accepted November 22, 2019.

ABBREVIATIONS AND ACRONYMS

AVR = aortic valve
replacement

BPV = bioprosthetic heart
valve

CT = computed tomography

TEE = transesophageal
echocardiography


THV = transcatheter heart
valve

TTE = transthoracic
echocardiography

fistulous connection between the left ventricular outflow tract and right ventricle on both TEE (**Figure 1D**, **Video 3**) and left ventriculography (**Video 4**). Hemodynamic stability was maintained throughout the procedure, and the contained rupture was concluded to be benign. After THV implantation, contrast-enhanced CT (2-dimensional [2D] and 3D reconstruction) confirmed a clear contrast leak at the level of the aortic neosinuses and the waist of the THV into the right ventricular outflow tract through the valve frame (**Figures 1E and 1F**). Within 12 h, the patient's hemodynamic status acutely deteriorated and required urgent re sternotomy as an inpatient (**Figure 1G**). The THV and original Perceval sutureless valves were retrieved and the aortic valve and root replacement procedures were redone (**Figure 1H**). The **Central Illustration** depicts the transcatheter heart valve inside the Perceval bioprosthesis and the anatomical position of the fistula. Perceval valve degeneration treated with valve-in-valve THV implantation has been previously reported (1). However, this is the first report of fistula formation following valve-in-valve transcatheter aortic valve replacement in this valve, despite appropriate sizing. There are limited data, but the ENCORE (European Contained Rupture Registry) would support a benign course of initially asymptomatic contained ruptures. This contained rupture was hypothesized to have occurred following THV expansion as a result of BPV frame protrusion and was associated with late hemodynamic collapse. Further experience is required particularly when performing valve-in-valve for structural degeneration of sutureless valves, despite good outcomes in published registry data (2,3).


ADDRESS FOR CORRESPONDENCE: Dr. Tiffany Patterson, Kings College London St. Thomas' Hospital, Cardiology, Westminster Bridge Road, London SE1 7EH, United Kingdom. E-mail: tiffany.patterson05@gmail.com.

FIGURE 1 CT Demonstrates Stent Infolding, Distortion, and Collapse of Perceval Sutureless Valve



(A) CT imaging demonstrates stent infolding, distortion, and collapse of Perceval Sutureless valve. (B) Left anterior oblique view of a Perceval Sutureless valve during right coronary angiography. (C) Orthogonal view of a successful Sapien S3 valve-in-valve implant. (D) Mid-esophageal long-axis view on TEE demonstrates a fistulous connection (white arrow shows color Doppler flow) between the right coronary cusp and right ventricle. Axial (E) CT imaging of well-deployed valve-in-valve with fistulous connection (white arrow) confirmed by contrast leak (F). This is also demonstrated by 3-dimensional CT reconstruction (white arrow). (G) Resternotomy for surgical AVR. (H) Sapien 3 (left) and Perceval Sutureless (right) valves retrieved perioperatively. AVR = aortic valve replacement; CT = computed tomography; TEE = transesophageal echocardiography.

CENTRAL ILLUSTRATION Image of the Patient's Cardiac Anatomy



Patterson, T. *et al.* *J Am Coll Cardiol Img.* 2020;2(2):309-11.

This demonstrates the heart in cross section, with the transcatheter heart valve (TAVR) implanted with the Perceval sutureless valve. The aorto-right ventricular fistula has created a shunt from the left ventricle (LV) to the right ventricle (RV). LA = left atrium; MV = mitral valve; RA = right atrium.

REFERENCES

- Landes U, Sagie A, Kornowski R. Transcatheter aortic valve implantation in degenerative sutureless perceval aortic bioprosthesis. *Catheter Cardiovasc Interv* 2018;91:1000-4.
- Landes U, Dvir D, Schoels W, Tron C, Ensminger S, Simonato M, *et al.* Transcatheter aortic valve-in-valve implantation in degenerative rapid deployment bioprostheses. *EuroIntervention* 2019;15:37-43.
- Dvir D, Webb JG, Bleiziffer S, *et al.* Transcatheter aortic valve implantation in failed bioprosthetic surgical valves. *JAMA* 2014;312:162.

KEY WORDS fistula, sutureless bioprosthesis, TAVR, valve-in-valve

APPENDIX For supplemental videos, please see the online version of this paper.